ings:

- Trash bins has no proper label
- Many flies in the area
- Without grease trap
- Lack of environmental permits such as Certificate of Non-Coverage (CNC), discharge permit and hazardous wastes generator I.D

In regards with the above-mentioned issue, MENRO cited the following recommendations to address the said issue. The lists of recommendations are as follows:

Recommendations:

- · Practice proper segregation of solid wastes
- Establish mini-Materials Recovery Facility (MRF) to serve as storage of generated wastes
- Trash bins must have proper label
- Maintain the cleanliness and apply organic spray to eliminate the flies in the area
- Install grease trap to collect the grease generated
- Accredited hauler for the proper disposal of liquid wastes or ensure that the liquid wastes generated is directly to the septic tank
- Secure environmental permits such as CNC (Certificate of Non -Coverage), hazardous wastes generator
 I.D, Cert. of final disposal for toxic and hazardous wastes and discharge permit to the EMB (Environmental Management Bureau)

Also, we will conduct quarterly monitoring on the said Establishment to ensure their compliance with the following environmental ordinances:

RA 9003-

Ecological Solid Waste Management Act of 2000

RA 8749-

The Philippine Clean Air Act

RA 9275-

The Philippine Clean Water Act

RA 6969-

Toxic Substances & Hazardous & Nuclear Waste Control Act

* We do advise to make an urgent response in addressing this matter as soon as you received this inspection report. Failure to comply with the recommendations given above will result to restricted operation or much worse, closure of the business.

Inspected by:

Arnold Mendoza

• Alvin Fernandez

Joven Guevarra

Mark Gil Roxas

Approved by:

EDGAR S. LUNA

MENRO

Noted by:

ENRIQUE V. TAGLE

Municipal Administrator



Pamahalaang Bayan ng Baliwag

MUNICIPAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

INSPECTION REPORT

Name of Establishment:

Yammyz Seafood

Address:

San Roque, Baliwag Bulacan

Issue:

Regular Inspection

Date of inspection:

July 05, 2022

Site Inspection:

July 05, 2022 (12:39 pm) conducted by Monitoring & Inspection

Team (MENRO)

Inspection report: Upon investigation, Monitoring & Inspection Team had come up with the

following observations and findings, to with













