

Findings:

- Has business permit
- Has 1 grease trap
- The liquid wastes from the extended kitchen flows to the canal
- Mixed wastes
- Has 10 trash bins
- Without environmental permit such as Certificate of Non-Coverage (CNC), Discharge Permit, Hazardous wastes generator I.D and Pollution Control Officer (PCO)

In regards with the above-mentioned issue, MENRO cited the following recommendations to address the said issue. The lists of recommendations are as follows:

Recommendations:

- Collected grease from grease trap must dispose by accredited private hauler
- Provide drum or IBC tank that will serve as container for the collected grease
- Always practice proper solid wastes segregation
- Avoid discharging of effluents to the drainage canal. Connect a pvc pipe from the grease trap going to the existing septic tank
- Submit septage and plumbing plan to check the flow of liquid wastes generated
- Secure environmental permits such as Certificate of Non-Coverage (CNC), Discharge Permit, Hazardous wastes generator I.D and Pollution Control officer (PCO) to the Environmental Management Bureau (EMB) or you can visit their website at r3.emb.gov.ph
- The permit holder shall submit quarterly self-monitoring report to City-ENRO

Also, we will conduct quarterly monitoring on the said Establishment to ensure their compliance with the following environmental ordinances:

- RA 9003- Ecological Solid Waste Management Act of 2000
- RA 9275- The Philippine Clean Water Act
- RA 6969- Toxic Substances & Hazardous & Nuclear Waste Control Act
- RA 8749- The Philippine Clean Air Act

** We do advise to make an urgent response in addressing this matter as soon as you received this inspection report. Failure to comply with the recommendations given above will result to restricted operation or much worse, closure of the business.*

Inspected by:

- Joven Guerra 
- Arnold Mendoza 
- Alvin Fernandez 
- Aldin Santos 

Approved by:

EDGAR S. LUNA, MSA
City- ENRO

Noted by:

ENRIQUE V. TAGLE
City Administrator