

LALAWIGAN NG BULACAN Pamahalaang Bayan ng Baliwag MUNICIPAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

INSPECTION REPORT

Name of Establishment:

Cornick Factory

Address:

Sulivan Baliwag Bulacan

Issue:

Follow-up Inspection

Date of inspection:


January 7, 2021

Site Inspection:

January 7, 2021 (10:11 am) conducted by Monitoring & Inspection

Team (MENRO)

Inspection report: Upon investigation, Monitoring & Inspection Team had come up with the following observations and findings, to with













Serbisyong May Malasakit!

YESI

Findings:

- Lack of trash bin
- No Grease Trap
- Improper construction of chimney
- Not functional drainage system

In regards with the above-mentioned issue, MENRO cited the following recommendations to address the said issue. The lists of recommendations are as follows:

Recommendations:

- Coordinate to (EMB) Environmental Management Bureau for the process of Certificate of final Disposal
- Proper Waste Segregation
- Additional trash bin for solid waste segregation
- Establish Grease Trap
- Establish higher chimney
- Proper installation of drainage system

Also, we will conduct quarterly monitoring on the said Establishment to ensure their compliance with the following environmental ordinances:

RA 9003-Ecological Solid Waste Management Act of 2000

RA 8749 The Philippine Clean Air Act RA 9275-The Philippine Clean Water Act

RA 6969-Toxic Substances & Hazardous & Nuclear Waste Control Act

* We do advise to make an urgent response in addressing this matter as soon as you received this inspection report. Failure to comply with the recommendations given above will result to restricted operation or much worse, closure of the business. (30 working days to comply)

This inspection report is certified on 11th of January, 2021.

Inspected by:

1. Arnold Mendoza

2. Kristian Gonzales

3. Mark Gil Roxas

4. Ryan Bautista

Approved by:

EDGAR S. LUNA MENRO

Noted by:

ENRIQUE V. TAGLE Municipal Administrator from hangares 1/14/2021