NAME OF ESTABLISHMENT: Romantic Batoy ADDRESS: Prt Hiway Pagala SUBJECT: Regular Inspection Municipal Requirements			DATE:	11/20/21 10:45 an	
ADDRESS: PH	HI WAY TAG	2010	-		
SUBJECT: Re	Autor PSP	quirements	estable to		With out
INDICATORS	With	Dat	e of coverage		Villa
ECC/CNC					
Sanitary Permit			100		
Mayor's Permit	PHONE .				-
Pollution Control Officer	- 113 W/	langgement	No.		NAME OF TAXABLE PARTY.
BROWN BOOK OF THE REAL PROPERTY.	Solid Wastes N	No	STATE OF	Remarks	
INDICATORS	tes				
Segregation at Source	1000 0000				
Segregated Bins		THO VENCE		1/2	(728-174
MRF		THE RESIDENCE			
Accredited Hauler		- NO WHERE		Use	
Cert. of Final Disposal					
IF APPLICABLE	A SECURIOR SEC		180	Dis	Checker.
Plastic Reduction	Liquid Wastes N	Management			
INDICATORS	Yes	No		Remarks	
Grease trap	or accepting				
Septic Tank	& Ore string	MO MENRO	1007	Mai	Election
Water treatment facility	100	No History	100	La Link	
Discharge Permit		HI CHARLES			
BOD Test				200	
Cubic meters/ day					
Acrredited Hauler		WORLDON.	700	080	
Cert. of Final Disposal	21 1 1 1 1 1 1 1 1	N S DO TO	Modical	Wastes Manag	ement
Toxic and Hazardous Wastes Ma		No	1 Wedical	Remarks	
CONTROL SECTIONS	Yes	10			Call Only the
Acrredited Hauler		Mary Andrews	2	200	Total La
Cert. of Final Disposal	- Comments				
ADDITIONAL REMARKS	Inspecto	ed by	C. 10 PT	Charles and Charles	
	The bound of the same				

CS CamScanner



LALAWIGAN NG BULACAN Pamahalaang Bayan ng Baliwag MUNICIPAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

INSPECTION REPORT

Name of Establishment:

Romantic Baboy

Address:

DRT Highway Baliwag Bulacan

Issue:

Regular inspection

Date of inspection:

November 22, 2021

Site Inspection:

November 22, 2021(10:47pm) conducted by Monitoring &

Inspection Team (MENRO)

Inspection report: Upon investigation, Monitoring& Inspection Team had come up with the following observations and findings, to with












System ISO 9001:2015

Rhoanger A. Peper

Serbisyong May Malasakit!



Baliwag Climate Change Center, DRT Highway, Pagala, Baliwag, Bulacan 3006



Findings:

- To follow environmental permits
- Has trash bin for solid wastes segregation
- Established septic tank

In regards with the above-mentioned issue, MENRO cited the following recommendations to address the said issue. The lists of recommendations to address the said issue. The lists of recommendations are as follows:

Recommendations:

- Secure environmental permits Secure environmental permits such as CNC (Certificate of Non Coverage) or ECC (Environmental Compliance Certificate)
- Installing of grease trap
- Must have discharge permit
- Secure Hazardous waste generator id
- Liquid waste must direct to septic tank
- The permit holder shall submit quarterly self- monitoring report to MENRO

Also, we will conduct quarterly monitoring on the said Establishment to ensure their compliance with the following environmental ordinances:

RA 9003-Ecological Solid Waste Management Act of 2000

RA 8749-The Philippine Clean Air Act RA 9275-The Philippine Clean Water Act

RA 6969-Toxic Substances & Hazardous & Nuclear Waste Control Act

* We do advise to make an urgent response in addressing this matter as soon as you received this inspection report. Failure to comply with the recommendations given above will result to restricted operation or much worse, closure of the business. (30 working days to comply)

Inspected by:

1. Arnold Mendoza

Alvin Fernandez

Mark Gil Roxas

Rowenna Ramire

5. Joven Guevarra

Approved by:

EDGAR S. LUNA

MENRO

Noted by:

ENRIQUE V. TAGLE

Municipal Administrator