

# LALAWIGAN NG BULACAN Pamahalaang Bayan ng Baliwag MUNICIPAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

## INSPECTION REPORT

Name of Establishment:

Pabs Sizzlers

Address:

DRT Highway Pagala

Issue:

Regular Inspection

Date of inspection:

March 3, 2022

Site Inspection:

March 3, 2022(1; 00 pm) conducted by Monitoring & Inspection Team

(MENRO)

Inspection report: Upon investigation, Monitoring& Inspection Team had come up with the following observations and findings, to with



























## Findings:

- The wastes in the trashbins are mixed
- Lack of Trash Bin (1)
- Without Septic Tank
- Lack of Environmental Permits
- Liquid Waste is Directly discharged to the open field
- Without PCO (Pollution Control Officer)

In regards with the above-mentioned issue, MENRO cited the following recommendations to address the said issue. The lists of recommendations are as follows:

### Recommendations:

- Additional Trash bin for proper Solid Waste Segregation
- Establish Septic Tank
- Secure Environmental Permits
- Send a Representative of your Establishment for PCO training

Also, we will conduct quarterly monitoring on the said Establishment to ensure their compliance with the following environmental ordinances:

RA 9003-

Ecological Solid Waste Management Act of 2000

RA 8749-

The Philippine Clean Air Act

RA 9275-

The Philippine Clean Water Act

RA 6969-

Toxic Substances & Hazardous & Nuclear Waste Control Act

\* We do advise to make an urgent response in addressing this matter as soon as you received this inspection report. Failure to comply with the recommendations given above will result to restricted operation or much worse, closure of the business.

#### Inspected by:

1. Arnold Mendoza

2. Joven Guevarra

Mark Gil Roxas

Ryan Bautista

Rowena Ramirez

6. Alvin Fernandez

Approved by:

EDGAR S. LUNA **MENRO** 

Noted by

ENRIQUE V. TAGLE

Municipal Administrator







Serbisyong May Malasakit!



