




LALAWIGAN NG BULACAN  
**Pamahalaang Lungsod ng Baliwag**  
CITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

**INSPECTION REPORT**

Name of Establishment: Planta Ivanka  
Address: Conception Baliwag Bulacan  
Issue: Regular inspection  
Date of inspection: July 18, 2023  
Site Inspection: July 18, 2023(10:00 am) conducted by Monitoring & Inspection Team (MENRO)

Inspection report: Upon investigation, Monitoring & Inspection Team had come up with the following observations and findings, to with




Management System  
ISO 9001:2015  
www.tuv.com  
ID: 9128643238



*Serbisyong May Malasakit!*

DUGONG  
BALIWAG  
PUSONG  
BALIWAG

Baliwag Climate Change Center, DRT Highway, Pagala, Baliwag, Bulacan 3006  
(044)798-0391 Loc. 3676 [menro@baliwag.gov.ph](mailto:menro@baliwag.gov.ph) [www.baliwag.gov.ph](http://www.baliwag.gov.ph)



**Findings:**

- Water treatment facility already established
- With mini MRF for proper solid waste segregation
- Complete trash bin
- Septic tank already established

**Conclusion:**

The above-mentioned establishment has passed all the measures pertaining to environmental protection. Therefore, Planta Ivanka located in Conception, Baliwag, Bulacan is certified COMPLIANT to environmental laws, regulations and standards.

**Recommended by:**

- Rowena Ramirez
- Joven Guevarra
- Alvin Fernandez

